


1948-56 Pickup Body Repair Parts

Street Rod Firewall and Front Floorboards




Fabricated steel

BN-481000	1948-52 Firewall: Smallblock	450.00 ea
BN-481002	1948-52 Floorboard kit	350.00 ea
BN-531000	1953-56 Firewall: Smallblock	525.00 ea
BN-531002	1953-56 Floorboard kit	350.00 ea

Transmission cover and floor

7C-700378	1948-52 Transmission cover, stock	not.avbl
7C-700378-T	1948-52 Transmission cover, extra tall	165.00 ea
BAAA-700378-T	1953-56 Transmission cover, extra tall	165.00 ea

1948-52 Pickup Patch Panels




7C-114-R	Cowl patch panel, RH	105.00 ea
7C-114-L	Cowl patch panel, LH	105.00 ea
7C-3114-PR	Door outer panel (body mount)	not.avbl
7C-3114-PR	Door inner panel (body mount)	not.avbl
7C-3114-PR	Door hinge post patch	not.avbl
8C-8140302-PR	Cab sill panels	50.00 pr
7C-8140302-PR	Cab corner patch	not.avbl
7C-8111105	Floor panel in front of seat	200.00 ea

1931-36

1937

1953-56 Pickup Patch Panels



BAAA-8102054-PR	Cowl patch panels	160.00 pr
BAAA-8102056-PR	Front body mounts	70.00 pr
BAAA-8102042-PR	Door pillar replacement (w/hinge pocket)	100.00 pr
BAAA-8120200-PR	Door outer patch panels	135.00 pr
BAAA-8120124-PR	Door inner patch panels	90.00 pr
BAAA-8110110-PR	Rocker panels	120.00 pr
BAAA-8140302-PR	Cab corner patches	100.00 pr
BAAA-8110112-PR	Cab to running board seal retaining channel	20.00 pr

1953-56 Floor

BAAA-839-FL	Cab front floor LH, 1953-55	not.avbl
BAAA-839-FR	Cab front floor RH, 1953-55	not.avbl
B6C-839-FL	Cab front floor LH, 1956	not.avbl
B6C-839-FR	Cab front floor RH, 1956	not.avbl
B6C-839-BHC	Battery hole cover plate 1956	not.avbl

* Parts with price listed as "not.avbl" are not known to be available at this time, but are listed for reference.