


1937-39 Passenger Headlights

Headlight

1937-39 Headlights are sold as components



	1937-38, 1939 Standard	1939 Deluxe & Mercury
Rim, stainless	78-13001-RM 30.00 ea	91A-13001-RM 30.00 ea
Lens, w/original fluting	78-13060 22.50 ea	91A-13060 22.50 ea
Lens, clear	78-13060-CL 30.00 ea	91A-13060-CL 30.00 ea
Lens gasket, cork	78-13066 1.50 ea	78-13066 1.50 ea
Lens gasket, rubber	78-13066-A 12.50 pr	78-13066-A 12.50 pr
Lens retainer bail	78-13067 12.50 pr	78-13067 12.50 pr
Bulb, 32/32cp 6 v	48-13007-A 1.50 ea	48-13007-A 1.50 ea
Bulb, 50/32cp 12v	48-13007-F 5.00 ea	48-13007-F 5.00 ea
Reflector (original style)	78-13028 27.50 ea	78-13028 27.50 ea
Reflector w/quartz bulb	78-13028-QH 75.00 ea	78-13028-QH 75.00 ea
Reflector retainer kit (w/springs & screws)	78-13030 50.00 ea	91A-13030 50.00 ea
Wiring socket, stock typ	78-13076 50.00 pr	78-13076 50.00 pr
Bucket kit, steel (includes reflector retainer, adjustment springs, and fender gasket)	78-13026-S 200.00 pr	91A-13026-S 200.00 pr
Bucket/fender cork	78-13044 10.00 ea	91A-13044 10.00 ea
Bucket/fender screws	01A-13026-HK 5.00 set	01A-13026-HK 5.00 set
Bucket lens/rim kit (hardware on bucket to mount lens and rim, enough for 1 bucket)	78-13061-K 17.50 ea	91A-13061-K 17.50 ea
Rim mt clip and screw	78-13026-R 7.50 ea	78-13026-R 7.50 ea

"Behind the Lens" Quartz Halogen System

Design for a clear glass lens. Lens is not in bucket kit, order separately


	1937-38	1939 Standard	1939 Deluxe & Mercury
Kit w/buckets	78-13026-QPR 325.00 pr		91A-13026-QPR 325.00 pr
Kit w/o buckets	78-13030-QK12 165.00 pr		91A-13030-QK12 165.00 pr

* Parts with price listed as "not.avbl" are not known to be available at this time, but are listed for reference.

1940 Ford/Mercury, 1940-41 Pickup Headlights and Parklights


Headlight Rims

1940 Deluxe, 1940 Mercury		
01A-13045	Chrome, die cast	150.00 pr
1940 Standard, 1940-41 Pickup w/hole for parklight		
01A-13045-A	Plain, die cast	180.00 pr
1940 Smooth		
01A-13045-AN	Plain, die cast	140.00 pr
HLD40P	Fiberglass	100.00 ea



Parklight Lens


01A-13084	Lens, 1940	7.50 ea
11C-13084	Lens, 1941 PU, wills 1940;	7.50 ea
01A-13085	Lens gasket	5.00 pr
01A-13082-CK	Lens retaining clip set	5.00 set
01A-13082	Bezel on rim, Chrome	75.00 pr



Headlight Buckets

Stamped steel, exact reproduction of the original bucket. Uses original type 7" seal beam bulb. Includes adjustment mechanism, bulb retainers, and bucket to fender gasket. Does not include bulbs or wiring sockets.

01A-13026-S	200.00 pr
-------------	-----------



Headlight Parts

01A-13044	Bucket to Fender Cork Gaskets	5.00 ea
01A-13026-HK	Bucket to fender bolts	5.00 set
01A-13026-R	Rim screw mount bracket repair kit, fixes 2 buckets	7.50 set
01A-13076	Internal wiring sockets	40.00 pr
01A-13032-HK	Focus screws and spring kit, fixes 2 headlights	17.50 ea
01A-13018-SS	Bulb retaining ring, stainless	15.00 ea
01A-13018-HK	Bulb retaining screws, set of 3	5.00 set

1941-48 Ford/Mercury, 1942-56 Pickup Headlights and Parklights

Headlight Rims

11A-13045	1941 Passenger	25.00 ea
21A-13045	1942-46 Pass, 1942-47 PU	25.00 ea
6A-13045	1947-48 Passenger	40.00 ea
B5C-13045	1948-52 Pickup, 1949-50 Pass	25.00 ea
B6C-13045	1956 Pickup	27.50 ea

Headlight Buckets

51A-13008	1941-48 Passenger, 1942-47 Pickup	not.avbl
1C-13008-A	1948-55 Pickup	75.00 ea

Headlight Bucket to Fender Cork Gaskets

11A-13044	1941-48 Passenger, 1942-55 Pickup	5.00 ea
-----------	-----------------------------------	---------

Headlight Internal Wiring Sockets

11A-13076	1941-48 Passenger	30.00 pr
0A-13076	1948-55 Pickup (rubber covered)	32.50 ea
51A-13077	1946-56 Headlight wire to bucket grommet	2.00 ea

Headlamp Sealbeam Bulb Retaining Parts

01A-13018-SS	Ring: 1940-56 Pass, 1940-56 Pickup	15.00 ea
01A-13018-HK	Screws (3): 1940-56 All	5.00 set

1941 Passenger Parklight

Black body, stainless trim, & glass lens.

11A-13200	Parklight	40.00 ea
11A-13217	Rubber Pad	10.00 pr



1942-46 Passenger Parklight

51A-13200	Parklight	not.avbl
51A-13217	Rubber Pad	25.00 ea


1942-48 Mercury Parklight

29A-13200	Parklight	not.avbl
29A-13217	Rubber Pad	20.00 pr

1942-47 Pickup & 1947-48 Passenger Parklight

Stainless steel rim, glass lens.


6A-13200	Parklight	32.50 ea
21C-13217	Cork Pad	7.50 pr
6A-13200-RP	Rubber Pad	12.50 pr



1948-50 Pickup Parklight

Stainless steel rim, glass lens.

7RC-13200	32.50 ea
-----------	----------



1951-56 Pickup Parklight

1C-13200-A	1951-52 PU, plain rim	32.50 ea
1C-13200-SS	1951-52 PU, stainless steel rim	40.00 ea
BAAA-13200-A	1953-54 PU, plain rim	35.00 ea
BAAA-13200-SS	1953-54 PU, stainless steel rim	40.00 ea
B5C-13200-A	1955 PU, plain rim	32.50 ea
B5C-13200-SS	1955 PU, stainless steel rim	40.00 ea
B6C-13200-A	1956 PU, plain rim	32.50 ea
B6C-13200-SS	1956 PU, stainless steel rim	40.00 ea

* Parts with price listed as "not.avbl" are not known to be available at this time, but are listed for reference.