


1938-47 Pickup and Truck Body Repair Parts

1938-39 Street Rod Firewalls and Front Floorboards Steel


Recessed Firewall:

Smallblock
BN-351000 475.00 ea



Floorboard & Trans Cover

use with smallblock firewall
BN-351002 350.00 ea




use with stock firewall
BN-351002-S 350.00 ea

1940-47 Street Rod Firewalls and Front Floorboards Steel


Recessed Firewall:

Smallblock:
BN-401000 425.00 ea
Bigblock:
BN-401000-4 475.00 ea



Floorboard & Trans Cover

use with smallblock firewall
BN-401002 375.00 ea
use with bigblock firewall
BN-401002-4 375.00 ea
use with stock firewall
BN-401002-S 375.00 ea



1938-39 Floor and Transmission Cover (original type)

81C-700378 Transmission cover 80.00 ea


1940-47 Transmission Cover and seals (original type)

01C-700378 Transmission cover, steel 75.00 ea
01C-700826 Transmission cover to floor seal 15.00 ea
01A-35190 Steering tube to floor seal, sponge rubber 5.00 ea
01C-8112145 Pedal & column seal cover plate set 30.00 ea

1940-47 Pickup Floor Panels


01C-835-TR Cab floor toe panel, RH 100.00 ea
01C-835-TL Cab floor toe panel, LH 100.00 ea
01C-835-C Floor center hump (behind trans cover) 50.00 ea
01C-835-FR Cab floor in front of seat, RH 1940-41 100.00 ea
01C-835-FL Cab floor in front of seat, LH 1940-41 100.00 ea
21C-835-FR Cab floor in front of seat, RH 1942-47 100.00 ea
21C-835-FL Cab floor in front of seat, LH 1942-47 100.00 ea
01C-855 Cab rear floor under seat, 1940-41 325.00 ea
(can be used 1942-47 if fuel tank not used)

Patch Panels



01C-114	Cowl patch panels, 1940-41	175.00 pr
01C-114-I	Cowl inner panels, 1940-41	115.00 pr
01C-114-HP	Hinge post patch, 1940-41	55.00 pr
01C-836	Door outer patch panels	85.00 pr
01C-836-I	Door inner patch panels, formed	45.00 pr
01C-836-IS	Door inner patch panels, die stamped	95.00 pr
01C-839	Cab sill panels	85.00 pr
01C-870-S	Cab corner patch	90.00 pr
01C-850-BACK	Cab back patch	60.00 ea

COE Cab Over Patch Panels



81Y-114	Cowl patch panels	150.00 pr
81Y-881-R	Inner fender panel, RH	150.00 ea
81Y-881-L	Inner fender panel, LH	150.00 ea
81Y-836	Door outer patch panels	60.00 pr
81Y-836-I	Door inner patch panels, die stamped	120.00 pr
81Y-870	Cab corner patch	130.00 pr
81Y-850	Cab back patch (no hump), 38-40	120.00 ea
11Y-850	Cab back patch with hump, 41-47	125.00 ea

* Parts with price listed as "not.avbl" are not known to be available at this time, but are listed for reference.